

mm to Inch Conversion Chart

mm	Inches (approximate)		
	Simple Conversion	To the nearest 1/32 inch	Decimal
1	1/32	1/32	0.04
2	1/16	3/32	0.08
3	1/8	4/32	0.12
4	3/16	5/32	0.16
5	3/16	6/32	0.20
6	1/4	8/32	0.24
7	1/4	9/32	0.28
8	5/16	10/32	0.31
9	3/8	11/32	0.35
10	3/8	13/32	0.39
11	7/16	14/32	0.43
12	1/2	15/32	0.47
13	1/2	16/32	0.51
14	9/16	18/32	0.55
15	9/16	19/32	0.59
16	5/8	20/32	0.63
17	11/16	21/32	0.67
18	11/16	23/32	0.71
19	3/4	24/32	0.75
20	13/16	25/32	0.79
21	13/16	26/32	0.83
22	7/8	28/32	0.87
23	7/8	29/32	0.91
24	15/16	30/32	0.94
25	1	31/32	0.98
26	1 1/32	1 1/32	1.02
27	1 1/16	1 2/32	1.06
28	1 1/8	1 3/32	1.10
29	1 1/8	1 5/32	1.14
30	1 3/16	1 6/32	1.18
31	1 1/4	1 7/32	1.22

32	1 1/4	1 8/32	1.26
33	1 5/16	1 10/32	1.30
34	1 5/16	1 11/32	1.34
35	1 6/16	1 12/32	1.38
36	1 7/16	1 13/32	1.42
37	1 7/16	1 15/32	1.46
38	1 8/16	1 16/32	1.50
39	1 9/16	1 17/32	1.54
40	1 9/16	1 18/32	1.57
41	1 10/16	1 20/32	1.61
42	1 10/16	1 21/32	1.65
43	1 11/16	1 22/32	1.69
44	1 12/16	1 23/32	1.73
45	1 12/16	1 25/32	1.77
46	1 13/16	1 26/32	1.81
47	1 14/16	1 27/32	1.85
48	1 14/16	1 28/32	1.89
49	1 15/16	1 30/32	1.93
50	1 15/16	1 31/32	1.97
51	2	2	2.01